

职业卫生评价项目信息网上公开表

用人单位 (建设项目)名称	澠池仰韶砭业有限责任公司	联系人	刘成剑
地理位置	河南省三门峡市澠池县黄花工业区。		
项目名称	澠池仰韶砭业有限责任公司职业病危害现状评价		
项目简介	澠池仰韶砭业有限责任公司成立于 2011 年，总投资 1000 万元。用人单位位于河南省三门峡市澠池县黄花工业区，占地面积约 15000m ³ ，现有工人 10 人，其中一线作业人员 4 人，主要经营范围是混凝土生产与销售。		
项目负责人	王伟超		
现场调查人	王伟超、杨淑娟		
现场调查时间	2023.8.19	用人单位陪同人	刘成剑
现场采样、检测人员	王伟超、王浩		
采样、检测 时间	2023.8.21~2023.8.23	用人单位陪同人	刘成剑
报告完成日期	2023.11.15	报告编号	DX/XP-ZP230811
用人单位 (建设项目)存在的职业 病危害因素及检 测结果	存在的职业病危害因素：粉尘、噪声 检测结果：用人单位皮带司机接触的呼吸性粉尘浓度超过职业接触限值，其他各工种接触的职业病危害因素浓度/强度均不超过职业接触限值。		
评价结论与建议	<p>结论：用人单位总体布局、生产工艺合理，部分设备布局不合理。辅助用室满足员工的使用需求，个体防护用品的发放满足相关标准规范要求，职业病危害防护设施满足相关标准要求，职业健康监护部分符合要求，职业卫生管理基本满足相关要求。</p> <p>建议：（1）加强空压机、搅拌机等高噪声设备的维护，定期加注润滑脂等。</p> <p>（2）加强设备、防护设施的管理和维护，定期和不定期进行检查，确保职业病防护设施能够正常、有效运转。</p> <p>（3）按照《工作场所职业卫生管理规定》和《职业卫生档案管理规范》，完善各个档案归档工作，按年度进行案卷归档，及时编号</p>		

	<p>登记，入库保管。</p> <p>(4) 加强应急救援物资的投入，进一步完善应急救援内容，根据应急救援预案内容进行应急救援演练，并做好演练记录。</p>
<p>技术审查专家组 评审意见</p>	<p>完善职业病危害因素检测结果和分析，完善应职业病防护设施和措施评价内容</p>
<p>现场影像资料</p>	 <p>The image block contains three photographs. The top photo shows three men in blue work clothes standing in an outdoor industrial yard with large buildings in the background. The middle photo shows a man in a blue uniform and a white face mask operating a piece of equipment with a screen and a camera lens. The bottom photo shows a man in a blue uniform operating a camera on a tripod in an industrial setting with a large blue structure and a yellow and black striped pillar.</p>